Seismic Upgrades and Building Alterations, Kensington Community Center

KCC Constuction Payment Status

Original Contract Sum	\$ 1,669,400
Application for Payment No. 1 (8/20/19)	\$ 80,750
Application for Payment No. 2 (9/26/19)	\$ 274,902
Application for Payment No. 3 (11-07-19)	\$ 254,466
Application for Payment No. 4 (12-12-19)	\$ 262,081
Application for Payment No. 5 (01-21-20)	\$ 248,266
Application for Payment No. 6 (03-10-20)	\$ 152,048
Balance Remaining	\$ 396,887

KCC Contingency Status

Proposed Change Approved Change Order Order		Notes / Status		
Original Contract Contingency			\$ 176,700	
CO 01 - Flooring & Lighting (Approved w/ Contract)	\$	36,707	\$ 36,707	
CO 02 - Power Conduit Revisions (Approved 9/29/19)	\$	1,639	\$ 1,639	
CO 03 - Excavation and Off-Haul (Approved 10/15/19)	\$	11,544	\$ 11,544	
CO 04 - Excavation and Backfill - Irrigation Line (10/09/19)	\$	7,372	\$ 3,830	
CO 05 - Fascia Materials Upgrade; Steel Adjustments (10/21/19)	\$	3,703	\$ 3,703	
CO 06 - Rework of Exposed Conduit, Main Hall (11/07/19)	\$	1,639	\$ 1,639	
CO 07 - Replace Damaged Interior Doors (11/09/19)	\$	2,691	\$ 2,691	
CO 08 - Replace Damaged Exterior Doors (11/12/19)	\$	4,927	\$ 4,927	
CO 09 - Heater Piping Enclosures & Soffit (11/21/19)	\$	4,937	\$ 4,937	
CO 10 - Misc. Electrical: Audio LV Wiring; Pantry DW Outlet;	\$	2,828	\$ 2,828	
Lighting Home-Run (11/26/19)				
CO 11 - Various Carpentry Items	\$	-	\$ -	
CO 12 - Replacement of damaged skylights and associated	\$	14,010	\$ 14,010	
carpentry & trim				
COR 13 - Repair/replace existing conduit at west roof eave	\$	1,138	\$ 1,138	
COR 14 - Sheetrock patch/repair/replacement for condensate	\$	4,946	\$ 4,946	
piping and conduit; associated painting				
COR 15 - Material revision/upgrade for Meeting. Hall ceiling	\$	4,140	\$ 4,140	
COR 16 - Power for lighting to future exterior sign location	\$	951	\$ 951	
COR 17 - Additional CMU demo at Nana-Wall steel frame	\$	3,939	\$ 3,939	
COR 18 - 66 Day addition to Contract Period Adjustment to	\$	-	\$ -	
contract period, adding 66 days due to unavoidable delays related				
to removal and disposal of contaminated soil plus coordination				
and clarifications related to windows and Nana-Wall installation				
and product lead times.				
COR 19 - Add sealer to cedar entry cover soffit finish	\$	1,748	\$ 1,748	
COR 20 - Planter wall retrofit (Scope addition)	\$	40,303	\$ -	Rejected; alternate methods under
,				review
COR 21 - Exterior light fixture substitution, all fixtures.	\$	4,878	\$ 4,878	
COR 22 - Bid alt flooring material change.		TBD		Under review
COR 23 - Replacement of leaking urinal and flush valve	\$	1,236		Under review
COR 24 - Additional painting - Cabinets at Meeting Room 2;	\$	3,447		Under review
Replacement Doors; Exterior light poles	•	-, -		
Balance Remaining			\$ 66,505	

Date: 03-23-20